

## CSAH 91 (Nicolai Av - Miesville): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
north city boundary	Morgan Cir	none	U		0.407	none	U		0.407	n/a	(a)	Miesville
Morgan Cir	TH 61	none	R		0.089	none	I		0.089	n/a	(a)	Miesville
TH 61	township split	none	U		0.250	none	U		0.250	n/a	(a)	Miesville
township split	south city boundary	none	U		0.623	none	U		0.623	n/a	(b)	Miesville
<b>TOTAL</b>				<b>0.000</b>	<b>1.369</b>			<b>0.000</b>	<b>1.369</b>		<b>Total Area</b>	<b>2.738</b>

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

### Notes

- (a) no shoulders
- (b) east half of highway is within Douglas Township

### Land Use

R	Residential (house, apartment)
C	Commercial (business, industrial)
I	Institutional (school, church, park, athletic complex)
U	Undeveloped (open space, utilities, transportation)

## CSAH 91 (Nicolai Av - Miesville): Pedestrian Ramp Inventory

CSAH 91 (Nicolai Av)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
Morgan Cir	0	0		6			Miesville
TH 61	0	0		6			Miesville
township split	0	0		6			Miesville
south city boundary	0	0		6			Miesville
<b>TOTAL</b>	<b>0</b>	<b>0</b>					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

### Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.

# CSAH 91 (Glendale Rd - Hastings): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
CSAH 54	Spiral Blvd	none	U		0.638	none	U		0.638	n/a	(a), (b)	Hastings
Spiral Blvd	south city bounday	none	U		0.305	none	U		0.305	n/a	(a), (b)	Hastings
<b>TOTAL</b>				<b>0.000</b>	<b>0.943</b>			<b>0.000</b>	<b>0.943</b>		<b>Total Area</b>	<b>1.886</b>

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

### Notes

- (a) driveways
- (b) narrow shoulders

### Land Use

- R** Residential (house, apartment)
- C** Commercial (business, industrial)
- I** Institutional (school, church, park, athletic complex)
- U** Undeveloped (open space, utilities, transportation)

## CSAH 91 (Glendale Rd - Hastings): Pedestrian Ramp Inventory

CSAH 91 (Glendale Rd)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
Spiral Blvd	0	1	for Spiral Blvd trail	3			Hastings
south city boundary	0	0		6			Hastings
<b>TOTAL</b>	<b>0</b>	<b>1</b>					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

### Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.