

CSAH 80 (240th St E - Hampton): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
west city boundary	CSAH 47	none	U		0.318	none	U		twp	n/a	(a), (b)	Hampton
CSAH 47	Hampton Blvd	none	U		0.504	none	U		twp	n/a	(a), (c)	Hampton
Hampton Blvd	TH 52 ramp	none	U		0.174	none	U		twp	n/a	(a), (b)	Hampton
TOTAL				0.000	0.996			0.000	0.000		Total Area	0.996

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Notes

- (a) south side of highway is in Hampton Township
- (b) no shoulders
- (c) rural residential with driveways

Land Use

R	Residential (house, apartment)
C	Commercial (business, industrial)
I	Institutional (school, church, park, athletic complex)
U	Undeveloped (open space, utilities, transportation)

CSAH 80 (240th St E - Hampton): Pedestrian Ramp Inventory

CSAH 80 (240th St E)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
CSAH 47	0	0		6			Hampton
Hampton Blvd	0	0		6			Hampton
TH 52 ramp	0	0		6			Hampton
TOTAL	0	0					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.

CR 83 (Dickman Av - Randolph): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
north city boundary	290th St E	none	U		0.313	none	U		0.313	n/a	(a), (b)	Randolph
290th St E	291st St E	none	R		0.080	sidewalk	R	0.080		fair		Randolph
291st St E	Upper 291st St	sidewalk	R	0.028		sidewalk	R	0.028		fair		Randolph
Upper 291st St	CSAH 88	sidewalk	R	0.045		sidewalk	R	0.045		fair		Randolph
CSAH 88	Doyle Tr	sidewalk	R	0.089		none	U		0.089	good		Randolph
Doyle Tr	south city boundary	none	U		gravel	none	U		gravel	n/a		Randolph
TOTAL				0.162	0.393			0.153	0.402		Total Area	1.110

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Notes

- (a) no shoulders
- (b) residential driveways

Land Use

- | | |
|----------|--|
| R | Residential (house, apartment) |
| C | Commercial (business, industrial) |
| I | Institutional (school, church, park, athletic complex) |
| U | Undeveloped (open space, utilities, transportation) |

CR 83 (Dickman Av - Randolph): Pedestrian Ramp Inventory

CR 83 (Dickman Av)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
290th St E	1	0		2			Randolph
291st St E	2	0		2			Randolph
Upper 291st St	2	0		2			Randolph
CSAH 88	0	0	included in CSAH 88 inventory	2			Randolph
Doyle Tr	0	0		6			Randolph
south city boundary	0	0		6			Randolph
TOTAL	5	0					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.

CSAH 85 (Goodwin Av - Vermillion): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
north city boundary	Reuter Dr	none	R		0.034	none	U		twp		(a)	Vermillion
Reuter Dr	CSAH 62	none	U		0.466	none	U		twp		(a)	Vermillion
CSAH 62	south city boundary	none	U		0.500	none	U		twp		(a)	Vermillion
TOTAL				0.000	1.000			0.000	0.000		Total Area	1.000

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Notes

- (a) east side of highway is Vermillion Township

Land Use

R	Residential (house, apartment)
C	Commercial (business, industrial)
I	Institutional (school, church, park, athletic complex)
U	Undeveloped (open space, utilities, transportation)

CSAH 85 (Goodwin Av - Vermillion): Pedestrian Ramp Inventory

CSAH 85 (Goodwin Av)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
Reuter Dr	0	0		6			Vermillion
CSAH 62	0	0		6			Vermillion
south city boundary	0	0		6			Vermillion
TOTAL	0	0					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.

CSAH 85 (Hogan Av - New Trier): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
TH 50	260' south	none	R		0.049	sidewalk	R	0.049		fair		New Trier
260' south	township split	none	U		0.040	none	R		0.040	n/a		New Trier
township split	south city boundary	none	U		0.098	none	R		0.098	n/a	(a)	New Trier
TOTAL				0.000	0.187			0.049	0.138		Total Area	0.374

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Notes

(a) west side of highway is Hampton Township

Land Use

R	Residential (house, apartment)
C	Commercial (business, industrial)
I	Institutional (school, church, park, athletic complex)
U	Undeveloped (open space, utilities, transportation)

CSAH 85 (Hogan Av - New Trier): Pedestrian Ramp Inventory

CSAH 85 (Hogan Av)	Curb Ramp Information						Location
At	Complies	To Comply	Notes	Case	Signal	Notes	City
260' south	0	0		6			New Trier
township split	0	0		6			New Trier
south city boundary	0	0		6			New Trier
TOTAL	0	0					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.

CSAH 88 (292nd St E - Randolph): Sidewalk Inventory

From	To	East/North	Land Use	Good/F Length	Poor Length	West/South	Land Use	Good/F Length	Poor Length	Rating (G/F/P)	Notes	City
CR 94	Curtis Ln	none	R		0.114	none	R		0.114	n/a	(a)	Randolph
Curtis Ln	Danel Av	none	R		0.136	none	I		0.136	n/a	(a)	Randolph
Danel Av	Davisson Av	none	R		0.061	trail	I	0.061		good	(a)	Randolph
Davisson Av	Dawson Av	trail	I	0.080		none	I		0.080	good	(a)	Randolph
Dawson Av	CR 83	sidewalk	R	0.080		none	R		0.080	good		Randolph
CR 83	Distad Path	sidewalk	R	0.027		none	R		0.027	good		Randolph
Distad Path	Divers Path	sidewalk	R	0.063		sidewalk	C	0.063		good		Randolph
Divers Path	CR 83	none	U		0.023	none	U		0.023	n/a		Randolph
CR 83	Douglas Av	sidewalk	C		0.028	sidewalk	R		0.028	poor		Randolph
Douglas Av	Duncan Av	none	R		0.172	none	R		0.172	n/a	(b)	Randolph
Duncan Av	east city boundary	none	R		0.114	none	U		0.114	n/a	(b)	Randolph
TOTAL				0.250	0.648			0.124	0.774		Total Area	1.796

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Notes

- (a) no shoulders
- (b) residential driveways

Land Use

R	Residential (house, apartment)
C	Commercial (business, industrial)
I	Institutional (school, church, park, athletic complex)
U	Undeveloped (open space, utilities, transportation)

CSAH 88 (292nd St E - Randolph): Pedestrian Ramp Inventory

CSAH 88 (292nd St E)	Curb Ramp Information					Location	
At	Complies	To Comply	Notes	Case	Signal	Notes	City
Curtis Ln	0	0		6			Randolph
Danel Av	0	0		6			Randolph
Davisson Av	3	0		2			Randolph
Dawson Av	2	0		2			Randolph
CR 83	2	0		2			Randolph
Distad Path	0	1		4			Randolph
Divers Path	0	2		4			Randolph
CR 83	0	0		6			Randolph
Douglas Av	0	0		6			Randolph
Duncan Av	0	0		6			Randolph
east city boundary	0	0		6			Randolph
TOTAL	7	3					

Shaded areas represent priority locations, areas of missing infrastructure and/or areas to address

Curb Ramp Case Ratings

- 1 Ramps with truncated domes that have been checked for compliance
- 2 Ramps that appear substantially compliant
- 3 Ramps without truncated domes
- 4 Ramps in need of construction installation or modification
- 5 Trail exists on one side of road. Trail is at grade & does not require ramps.
- 6 No pedestrian facilities exist.